

<b>Technical Information</b>	Date: 06.11.2023 Official: Heckl Department: BT-FS/MKP3
------------------------------	---------------------------------------------------------------

<b>Tech. Information No.</b>	2554 / 2023
<b>Subject:</b>	FPP 5000 / Wrong wiring on power supply holder

<b>Short Description:</b>	<p>On a FPP 5000 a wrong wiring on power supply holder was detected. In the pre-installed cable, the L1 (brown wire) and protective ground (green-yellow wire) were mixed up.</p> <p><b>Attention life safety risk:</b> Electrical hazard may occur!</p> <p>Successfully commissioned installations are not affected. a</p>
---------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

<b>Hardware</b> <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Device	<input checked="" type="checkbox"/> Module	<input type="checkbox"/> PCBA
<b>Software</b> <input type="checkbox"/>	<input type="checkbox"/> Application	<input type="checkbox"/> Driver / Extension	<input type="checkbox"/> Firmware

Affected Products (details)	CTN	SAP no.	Aff. version	New version
External power supply kit	FPP 5000	F.01U.511.307		
Mounting frame for power supply, medium	PMF 0002 A	F.01U.511.306		

<b>Number of delivered devices</b>		
<b>Period of delivery</b>	from:	to:.
<b>Affected serial numbers</b>	from:	to:

Priority Level	Criterion
I	<input type="checkbox"/> The change has to be made <b>immediately</b> (see dates below)
II	<input type="checkbox"/> The change has to be made during the next inspection.
III	<input checked="" type="checkbox"/> Change has to be made, if the error pattern recurs and with new installations.
None	<input type="checkbox"/> General Information (like new tool, new feature, new SW release)



Action Plan	
<input checked="" type="checkbox"/>	Inform customers
<input type="checkbox"/>	Arrange re-work of stock (CSO)
<input checked="" type="checkbox"/>	Arrange re-work of stock (customer)
<input type="checkbox"/>	Arrange re-work of installed products
<input checked="" type="checkbox"/>	See detailed actions on following pages

Print out of this template is not subject of the updating service. Only the version in the Intranet is always up to date.

<b>Start Date</b>	<b>Immediately</b>	<b>Completion Date</b>	
-------------------	--------------------	------------------------	--

**Detailed Actions:**

For new installations, before connecting the power supply unit to mains voltage, the correct internal wiring of the power cable needs to be checked. If the error pattern occurs, the wiring has to be changed to the correct wiring.



<b>Removed features:</b>

<b>Solved Issues:</b>

<b>Notes:</b>

Required Components	Part no.

<b>Attachment(s)</b>

<b>BU Manager</b>	Thomas Knauel	<b>Clerk in Charge:</b>	Michael Heckl
<b>Distribution</b>			
Distribution BU FIR Fire Systems	<input checked="" type="checkbox"/>	Ivan Martinko (BT/QMM-FS), Gerhard Puechler (BT/QMM-FS), Andreas Speich (BT/QMM-FS)	
	<input checked="" type="checkbox"/>	Thomas Knauel (BT-FS/MKP BT-FS/PJ-PG), Kristof Vandenberghe (BT-FS/MKP1), Bernd Harbers BT-FS/MKP1)	
	<input checked="" type="checkbox"/>	Ron Marier (BT-FS/MKP3), Michael Heckl (BT-FS/MKP3)	
	<input checked="" type="checkbox"/>	Josef Angstenberger (BT-FS/MKR-EU), Jakub Bednarz (BT-FS/MKR-EU BT-FS/MKA- EU)	
	<input checked="" type="checkbox"/>	Kah Seong Ong (BT-FS/SAM-AP BT-FS/MKR-AP), Leonard Hew (BT-FS/MKR-AP)	
	<input checked="" type="checkbox"/>	Renato Lima (BT-FS/MKR-LA), James Mottorn (BT-FS/MKP-AM)	
Other parties affected	<input checked="" type="checkbox"/>	Felix Schrimpf (BT-ASA/MKP BT-ASA/MKC)	
	<input checked="" type="checkbox"/>	Konrad Proyer (BT-ASA/MSR-Sab), Andre Dias (BT-ASA/SRA-LA), Jim Wilson (BT-ASA/TCR-Lio BT-ASA/MSR2-Lio), Khiang Tan Woo (BT-ASA/SRA-AP)	
	<input checked="" type="checkbox"/>	Manjit Gill (BT-ASA/STS2-EU)	
	<input type="checkbox"/>	Teleservice Support (SO/OPM8.10Mb)	
	<input checked="" type="checkbox"/>	Holger Behrens (BT-IE/SPM-SF)	
	<input checked="" type="checkbox"/>	Petra Adelman (BT-IE/CTA-CSS1)	
	<input checked="" type="checkbox"/>	David Ziegler (BT-IE/SPM-SF), Ines Schittenhelm (BT-IE/SPM-SF), Michiel de Graaf (BT-IE/XSP-NL), Jaap Smit (BT-IE/XSP-NL), Productmanagement.sn1@nl.bosch.com (BT-IE/XSP-NL)	